In the specification on page 4, lines 1-3:

The heated fat 12 fat 10 under pressure of 20-80 pounds per square inch is applied to the falling granules of anhydrous potassium carbonate until the granules are coated with approximately 1-5% by weight of the fat (FIG. 2).